1		2	3	3	4		5	6	
	Surface	Screw (quantity)	Washer (quantity)	Spring washer (quantity)	<b>Nut</b> (quantity)	Package	Notice		
F-GSCH1/5-K130	zinc plated 1)	2	4	2	2	in pairs	Packed together in a bag		
F-GSCH1/5-K130SN	tin plated	2	4	2	2	in pairs	Packed together in a bag		
F-GSCH1/5-K130S	zinc plated 1)	max. 5000	max. 10000	max. 5000	max. 5000	bulk packed	Individually packed in bag		
F-GSCH1/5-K130SSN	tin plated	max. 5000	max. 10000	max. 5000	max. 5000	bulk packed	Individually packed in bag	·	_
F-GSCH1/5-K130N	zinc plated 1)	2	4	2	2	in pairs	Packed together in a bag		
F-GSCH1/5-K1114	tin plated		4	1	<u>-</u>		Threaded insert (F52M122M		
		4-40UNC-2B	3.1 Length of engagement	-	12.7	4-40UNC-2A			
		SW 4,5	4.7			4-40			_
			4.7		DRAWN 04-0	ement without nice occ. to 2768-m 5:1 DATE NAME 09-2002 schref 09-2002 Floßmann	F-GSCH1/5 K	crew lock (130 4-40/4-40	- R